

RECEIVED
FEB 3 1976
WATER RIGHTS

NINE MILE WATER DISTRIBUTION

1975

May 15.

Nutters - Upper diversion North side	2.60
Wimmer - Harmon Place	3.10
Pressett	2.10
Burdick	2.60
Mills	No water
H. J. Wimmer (approximately)	7.00
Wimmer - Davis Place	4.60
Iron Cross - Christensen Place	No water
Hammerschmidt	No water
Keel	No water

Because of the extremely wet spring and the creek running high I could not cross to check some of the measuring devices on the south side and could not check them up Minnie Maude.

June 14

Bryner	No water
Motte	2.25
Keel	2.53
Hammerschmidt	No water
Iron Cross - Christensen Place	3.00
Wimmer - Davis Place	2.60

June 15

Nutter - Upper North side	1.84
Upper South side	2.75
Lower	No water
Iron Cross - Alger Place	No water
Wimmer - Harmon Place	3.50
Pressett	1.75
Burdick	2.00
Mills (approximately)	3.00
H. J. Wimmer	No water

July 24.

Bryner	2.50
Motte	.15
Keel	1.40
Hammerschmidt	No water
Iron Cross - Christensen Place	No water
Wimmer - Davis Place	4.10
H. J. Wimmer (approximately)	1.00
Mills (approximately)	3.60
Burdick	1.40
Pressett	2.20
Wimmer - Harmon Place	3.80
Nutter - Upper diversion North	1.65
Upper diversion South	3.20

Nine Mile Water Distribution
page 2.

Nutter - Lower Diversion		No water
Iron Cross - Alger Place		No water
Lower Ranch		No water
Flying Diamond	(approximately)	5.50

August 24.

Bryner		2.10
Motte		2.60
Keel		1.80
Hammerschmidt		2.30
Iron Cross - Christensen Place		No water
Wimmer - Davis place		3.50
Wimmer - Harmon Place		4.25
Pressett		1.30
Burdick		1.10
Mills - Upper diversion	(approximately)	1.40
Lower diversion	"	2.60
H. J. Wimmer	"	4.50
Nutter - Lower diversion		.75
Upper diversion north		2.20
Upper diversion south		2.60
Iron Cross - Alger Place		No water
Lower Place		No water
Flying Diamond - Lower diversion		3.50
Upper diversion		No water

Sept. 18.

Flying Diamone - Lower diversion		3.00
Upper diversion		No water
Iron Cross - Lower Ranch	(approximately)	3.50
Nutter - Lower diversion		1.10
Upper diversion North		1.80
Upper diversion South		2.40
Iron Cross - Alger Place		4.20
Wimmer - Harmon Place		3.10
Pressett		1.25
Mills	(approximately)	3.25
H. J. Wimmer	"	2.50
Wimmer - Davis Place		2.80
Iron Cross - Christensen Place		No water
Hammerschmidt		No water
Keel		.75
Motte		.30
Bryner		1.20

Nine Mile Water Distribution
Page 3.

<u>DATE</u>	<u>MILES</u>	<u>HOURS</u>
May 15	42	4½
June 14	24	2½
June 15	28	3
July 24	60	5
August 24	60	5
Sept. 18	60	5
Total	274	25

The following water users either need to install or level their measuring devices;

Bryner - Measuring device not level.

Motte - Measuring device is too low. Water backs up into it.

Henry Mills - Measuring device not in ditch

H. J. Wimmer - Measuring device not in ditch.

Iron Cross - Lower Ranch - No measuring device.

Flying Diamond - No measuring device.

Jerry Burdick
Water Commissioner - 1975.